# Instructions for Installation of MBS Waldram Tools V6.0

- Required setup files can be downloaded from here.
  https://www.mbs-software.co.uk/downloads/waldramtools

- Click Autocad Version tab

- Download the installation package **AcadWaldramTools Setup.exe**

    - Please **Close** Autocad and all **MBS** console services and wait for 60 seconds to allow the files to be released.

    - The **AcadWaldramToolsSetup.exe** file **must** be run by Right Clicking the file and Selecting **Run as Administrator** option.
      This ensures future updates can be obtained without admin permission.

    - It installs the drivers for Des key licensing dongle, .Net framework, Report Viewer and Radiance dependencies along with the Waldram tools DLL and settings files.

    - Remember to Select *Add radiance to the system PATH for all users*.

    - The DLL files are copied to *Autocad* folder in *Program files* commonly

      C:\Program Files\Autodesk\ApplicationPlugins\Waldram.bundle

    - The setting files are **now** copied to the *MBS* folder in *ProgramData* commonly
      C:\ProgramData \MBS Software